

CARON FIELD SERVICE

On-site repairs for minimum downtime.



Cut equipment downtime with on-site service and repairs:

Pin-On® Cap Changes
Teeth/Cleat Removal and Installation
Outer Drum Edge Hardfacing
Inner Cone Wear Bar Installation
Inner Cone Replacement
Wheel Rotation

Wheel Welding Repair
Center Hinge Guard Installation
Axle Safeguard Group™ Installation
Seal Protection Group™ Installation
Trashblade Repair and Maintenance
Track Shoe Installation and Rebuild



Each Caron Service Truck is Fully Equipped:

Model T-800B Kenworth Conventional with 62" Aerocab Sleeper
Caterpillar 3406E engine rated at 475 hp
13-speed Fuller Transmission
Eaton Axles - 14,600 lbs. rated front and 40,000 lbs. rear axle
Full Neway Air Suspension

Features include:

National Model N105 Knuckle Boom Hoist with 180 degree service rated capacity of 15,000 lbs. Useful capacity of 5,500 lbs. at 20 ft. radius
Multi-Quip 180 CFM Compressor
Two Lincoln 400 AMP welding Machines with LN-8 wire feeders.
Four Reelcraft Hose Reels (Two 3/4" and 1/2" lines)
Oxygen and Acetylene in enclosed cabinet with hose reel.
Wire feed cabinet with lifting boom for ease and speed at hauling.

No need for your personnel to spend time and money to remove and replace wheels or pay freight for repairs to dealers/manufacture.



CARON®
COMPACTOR COMPANY

809 Sylvan, Suite 500
Modesto, CA 95350-1500 USA
(209) 578-9514, (800) 448-8236 (US and Canada)
Fax (209) 578-2833, (800) 68-CARON
eMail: sales@caroncompactor.com
www.caroncompactor.com